



17th Annual PQSynergy™ International Conference and Exhibition 2017

Impact of Power Quality on Rice Mills




IMPACT OF POWER QUALITY ON RICE MILLS




Protection Equipment




High Voltage Side



Low Voltage Side At MDB



● UVT circuit diagram



Control part



Start Motor By Star - Delta

Control part




Inverter



Control Speed Drive


Rice Milling process



Position of Setting PQ monitoring

(19 Dec 57 - 3 Feb 58)


1 st



Volt



2 nd





17th Annual PQSynergy™ International Conference and Exhibition 2017

Electric Power Statistics From PEA

Date	Time	FEEDER	status	Cause
9 Jan 2015	14:41:00	PTU03	T/R1	Assumed Animal (IF=1446A)
31 Jan 2015	9:38:00	PTU03	T/R1	Accident from building site zone Pratan Market



Electric Power Statistics From Rice Mill

Date	Time	Rice Mill
9 jan 2015	14.44	interruption
31 jan 2015	9.43	Outage



17th Annual PQSynergy™


International Conference and Exhibition 2017



9 Jan 2015 Time 14:42:06 Dip 7 %

Date	Time	Feeder ID	Com	Protection	Caption	Additional	wheather
			ID2	Alarm			
9-01-2015	2:41:00	PTU03	PTU06VB-01	Overcurrent Relay	T/R1	Assumed Animal (IF=1446A)	Nomal

17th Annual PQSynergy™ International Conference and Exhibition 2017




31 Jan 2015 Time 09:38:23 Interruption

Date	Time	Feeder ID	Com	Protection	Caption	Additional	wheather
			ID2	Alarm			
31-01-2015	9:38:00	PTU03	-	Overcurrent Relay	T/R1	Accident from building site zone Pratan Market	Nomal

Suggestion

1. **Change Voltage Relay in control part from single phase coil to 3 phase Coil.**



2. Rice Mill has made Shutter for protect whitening process.



Additional in 2017

1. **Manager of Rice Mill found every time they have dip event. Magnetic contactor will break down always. So PEA suggest Change Start Motor from Star – Delta type to soft start and install Coil Lock equipment for protect Magnetic contactor break down.**



Coil Lock

2. Rice mill has problem : Inverters can't operate when have dip event.

PEA suggest install function restart auto into inverters or install online UPS for control part of inverters.



Online UPS



Thank You

